



REPORT TO THE AMENITIES COMMITTEE

19 FEBRUARY 2026

Storm Goretti Damage Report

1. Plantation

Emergency tree works carried out to storm damaged branches on large Pinus Radiata trees hanging over the road. There were also multiple additional windblown trees and large fallen limbs.

A large section of chestnut paling fence has been damaged beyond economical repair, the replacement of a 35m x 1.2m will need to be undertaken due to Health and Safety concerns.

Cost of tree work	£2,686 (Greens Grounds & Trees)
Cost of Fencing work	£2,137 (Cormac)

2. Millpond

Emergency works to remove several windblown trees. Additional lower priority job requiring a tractor and winch for windblown tree currently in the water.

Trees	£607 (Greens Grounds & Trees)
Additional work	£tbc (Greens Grounds & Trees)

3. Recreation Ground

Work carried out to damaged branches in large Poplar tree over the play area.

Trees	£227.70
-------	---------

4. King George V Memorial Walk

Several damaged trees over hanging the walk from the banking, the Gardening team have cut back the overhanging branches and the branches resting on the decorative lights cable.

5. Swimming Pool

The swimming pool fence facing the car park was blown over, there is extensive damage to the timber posts which will all need to be replaced.

Fence	£2,000 (estimate in-house)
-------	----------------------------

6. Community Centre

There were multiple roof tiles blown off the roof, thankfully no users of the Community Centre were injured and there was also no damage to the property or any vehicles.

Replacement roof tiles	£450 (JS Roofing)
------------------------	-------------------

7. Library

The library sustained damage to the rear of the building with several tiles blown off the roof.

Replacement roof tiles	£550 (JS Roofing)
------------------------	-------------------

Brandon Walters (Facilities and Contracts Manager)



REPORT TO THE AMENITIES COMMITTEE

19 February 2026

Recreation Ground New CCTV Cameras

Two new cameras have recently been installed at the Recreation Ground, the cameras are now live and linked up to our monitoring station in St Ives. Signage will be displayed at various locations around the Recreation Ground park informing the public that 24-hour CCTV is in operation.



Replacement of CCTV Cameras

There are two CCTV cameras that are currently out of action and beyond economical repair due to their age. These cameras are located on Penpol Terrace and Copper Terrace, there is currently no CCTV coverage in these areas.

The new CCTV cameras at the Recreation Ground were originally going to be funded by the Community Infrastructure Levy (CIL) funding. Subsequently, HTC managed to secure a grant for £10,000 from the Police and Crime Commissioner to pay for this work. The Community Infrastructure Levy (CIL) funding is now available to use for a different project.

Recommendation:

1. To approve the use of the Community Infrastructure Levy grant to fund the replacement CCTV cameras at both Penpol Terrace and Copper Terrace.

Brandon Walters (Facilities and Contracts Manager)

Appendix 1 - Enerveo CCTV Camera Quotes